MATERIAL SAFETY DATA SHEET

This MSDS complies with OSHA'S Hazard Communication Standard 29 CFR 1910.1200 and OSHA Form 174 IDENTITY AND MANUFACTURER'S INFORMATION HMIS Rating: Health-2; Flammability-3; Reactivity-0; Personal Protection-B NFPA Rating: Health-2; Flammability-3; Reactivity-0; Special-0 DOT Hazard Classification: ORM-D Manufacturer's Name: AMREP, INC. Identity (trade name as used on label): MISTY VANDALISM MARK REMOVER +2356 03168 990 Industrial Park Drive Address: Marietta, GA 30062 MSDS Number: 178 Revision-11 Prepared By: DL Date Prepared: 12/03/97 NOTICE: JUDGEMENT BASED ON INDIRECT TEST DATA Information Calls: (770)422-2071 EMERGENCY RESPONSE NUMBER: 1(800)255-3924 SECTION 1 - MATERIAL IDENTIFICATION AND INFORMATION OSHA PEL ACGIH Carcinogen SARA COMPONENTS-CHEMICAL NAMES AND COMMON NAMES CAS Number Ref. Source * III LIST (ppm) TLV (ppm) Hazardous Components 1% or greater; Carcinogens 0.1% or greater) 100 d Yes 200 108-88-3 750 d 67-64-1 No 1000 **ACETONE** 25 d 111-76-2 Yes 25 ETHYLENE GLYCOL N-BUTYL ETHER 1000 1000 d No 74-98-6 PROPANE 78-93-3 Yes 200 200 d METHYL ETHYL KETONE WARNING: This product contains a chemical or chemicals known to the State of California to cause cancer, birth defects or other reproductive harm. SECTION 2 - PHYSICAL/CHEMICAL CHARACTERISTICS Specific Gravity (H2O=1): Concentrate Only = .84 Boiling Point: N/A Vapor Pressure (Non-Aerosols)(mm Hg and Temperature): N/A Vapor Pressure: PSIG @ 70°F (Aerosols): Max.60 N/E Evaporation Rate (Vapor Density (Air = 1): N/E Water Reactive: No Solubility in Water: Partial Appearance and Odor: Clear liquid, aromatic solvent odor. SECTION 3 - FIRE AND EXPLOSION HAZARD DATA Flammability Limits in Air by % in Volume: FLAMMABILITY as per USA FLAME PROJECTION TEST Auto Ignition Temperature % UEL: N/E N/E % LEL: N/E EXTREMELY FLAMMABLE EXTINGUISHER MEDIA: Foam, dry chemical, carbon dioxide, water. FLASH POINT AND METHOD USED (non-aerosols): N/A SPECIAL FIRE FIGHTING PROCEDURES: Self-contained breathing apparatus. Unusual Fire & Explosion Hazards: Do not expose aerosols to temperatures above 130°F or the container may rupture. SECTION 4 - REACTIVITY HAZARD DATA HAZARDOUS POLYMERIZATION [] WILL [X] WILL NOT STABILITY [X] STABLE [] UNSTABLE Conditions to Avoid: Open flame, welding arcs, heat, sparks. Incompatibility (Mat. to avoid): Acids and strong oxidizers Hazardous Decomposition Products: CO, CO2 SECTION 5 - HEALTH HAZARD DATA PRIMARY ROUTES OF ENTRY: [X]INHALATION []INGESTION [X]SKIN ABSORPTION []EYE []NOT HAZARDOUS ACUTE EFFECTS: Inhalation: Excessive inhalation of vapors can be harmful and may cause headache, dizziness, asphyxia, anesthetic effects and possible unconsciousness. Skin Contact: Irritation Eye Contact: Irritation Ingestion: Possible chemical pneumonitis if aspirated into lungs. Nausea. CHRONIC EFFECTS: (Effects due to excessive exposure to the raw materials of this mixture) May cause cardiac abnormality, liver abnormalities, kidney and/or lung damage. Lab animals have experienced anemia, liver, kidney, lung, blood damage to Glycol Ether EB. Medical Conditions Generally Aggravated by Exposure: May aggravate existing eye, skin, or upper respiratory conditions. **EMERGENCY FIRST AID PROCEDURES** Eye Contact: Flush with water for 15 minutes. If irritated, seek medical attention. Skin Contact: Wash with soap and water. If irritated, seek medical attention. Inhalation: Remove to fresh air. Resuscitate if necessary. Get medical attention. Ingestion: DO NOT INDUCE VOMITING. Drink two large glasses of water. Get immediate medical attention SECTION 6 - CONTROL AND PROTECTIVE MEASURES Respiratory Protection (specify type): If vapor concentration exceeds TLV, use respirator approved by U.S. Bureau of Mines for organic vapor. Eye Protection: Safety glasses recommended. Protective Gloves: Rubber gloves. Ventilation Requirements: Adequate ventilation to keep vapor concentration below TLV. Other Protective Clothing & Equipment: None Hygienic Work Practices: Wash with soap and water before handling food. Remove contaminated clothing. SECTION 7 - PRECAUTIONS FOR SAFE HANDLING AND USE Steps To Be Taken If Material Is Spilled Or Released: Absorb with suitable medium. Incinerate or landfill according to local, state or Federal regulations. Prevent from entering drains or sewers. Waste Disposal Methods: Aerosol cans when vented to atmospheric pressure through normal use, pose no disposal hazard. Precautions To Be Taken in Handling & Storage: Do not puncture or incinerate containers. Do not store at temperatures above 130°F. Other Precautions &/or Special Hazards: KEEP OUT OF REACH OF CHILDREN. Avoid food contamination. Avoid breathing vapors. Remove ignition sources. We believe the statements, technical information and recommendations contained herein are reliable, but they are given without warranty or guarantee of any kind.

Chemical Listed as Carcinogen or Potential Carcinogen. [a] NTP [b] IARC Monograph [c] OSHA [d] Not Listed [e] Animal Data Only